

## Document Log Item

<b>Addressing</b>	
<b>From</b>	<b>To</b>
Carl Goldstein/R9/USEPA/US	Allan Ota/R9/USEPA/US@EPA Sara Greiner/R9/USEPA/US@EPA Allan Ota/R9/USEPA/US, Sara Greiner/R9/USEPA/US
<b>CC</b>	<b>BCC</b>
<b>Description</b> <span style="float: right;">Form Used: Memo</span>	
<b>Subject</b>	<b>Date/Time</b>
Fw: High Strength Tank Leak at COS	08/24/2007 09:26 AM
<b># of Attachments</b>	<b>Total Bytes</b>
8	1,319,940
<b>NPM</b>	<b>Contributor</b>
	Marcela VonVacano
<b>Processing</b>	
<b>Comments</b>	

Body

## Document Body

----- Forwarded by Carl Goldstein/R9/USEPA/US on 08/24/2007 09:25 AM -----

"Jim Cox" <jcox@cosintl.com>

08/23/2007 08:29 PM

To: Carl Goldstein/R9/USEPA/US@EPA, <pjp617@uow.edu.au>  
cc: "SAM Willem Martins" <wmartins@sampac.com>, "SAM Ken Mcleod" <kmcleod@sampac.com>  
Subject: High Strength Tank Leak

I have attached a write-up giving an account of the incident and also attached some pictures of the normal tank bottom, repair area, and the pipe return from catchment sump to line to HS tank.



SampacJune2007 095.JPG



SampacJune2007 088.jpg



SampacJune2007 089.JPG



SampacJune2007 090.JPG



SampacJune2007 091.JPG Sa